

5. Using Putty Knife, fill screw holes with **6.** Medallion can be painted with Latex Latex Caulking

or Oil Base Paint